

Vehicle Test Report(VTR)

元征 LAUNCH

Detection Device: X-431 PRO ELITE
(SN:987947742068)
Detection Time: 2026-09-10 10:49:12
Report Type: Pre-Repair



Land Rover Evoque(L538)

2015 130148 km

VIN: SALVA218 [REDACTED]
Vehicle Software Version: V35.17
Diagnostic Application Version: V8.00.048
Diagnostic path: > Status Report > ACM (Audio Front Control Module)

Repair Shop

Shop Name: Checkauto
Address: Montreux Monteux Vaud Switzerland
Zip Code: 1820
Telephone: +41795897777
Email: autocheck@gmail.com
SN: 987947742068
Test Time: 2026-09-10 10:49:12
Technician Name: Sergey



Data Stream 【Pre-Repair】

Name	Value	Standard Range	Unit
Adjacent Radio Station Interference Noise	127	0 - 429496729	
Audio Unit Frequency Field Strength	37	0.00 - 0.26	dB
Bluetooth Remote Device Information - Current Battery Level	255	0.00 - 0.26	%
Bluetooth Remote Device Information - Maximum Battery Level	100	0.00 - 0.26	%
Bluetooth Remote Device Information - Minimum Battery Level	20	0.00 - 0.26	%
Bluetooth Remote Device Information - Signal Strength	0	0.00 - 0.26	%
Bluetooth Signal Quality - Current Value	255	0.00 - 0.26	%
Bluetooth Signal Quality - Maximum Value	92	0.00 - 0.26	%
Bluetooth Signal Quality - Minimum Value	0	0.00 - 0.26	%
Bluetooth Telephone Network Information - Current - Signal Strength	255	0.00 - 0.26	%
Bluetooth Telephone Network Information - Maximum - Signal Strength	0	0.00 - 0.26	%
Bluetooth Telephone Network Information - Minimum - Signal Strength	100	0.00 - 0.26	%

Compact Disc Player Internal Temperature	20	-40 - 215	degC
Critical Unlock Count	5	0 - 65535	
Digital Disk Player - Media Error Statistics - Number Of DVD Disc Tray Load Error	0	0 - 65535	
Digital Disk Player - Media Error Statistics - Number Of DVD Mechanism Position Not Read	0	0 - 65535	
Digital Disk Player - Media Error Statistics - Number Of Servo Focus Error	0	0 - 65535	
Digital Disk Player - Media Error Statistics - Number Of Subcodes That Cannot Be Read	0	0 - 65535	
Digital Disk Player - Media Error Statistics - Number Of Table Of Content Read Errors	0	0 - 65535	
Fan Speed - Commanded	0	0 - 255	%
Handsfree Connection Error	5472	0 - 65535	
Number Of Paired Bluetooth Devices	3	0 - 255	
Number Of Trouble Codes Set Due To Diagnostic Test	0	0 - 255	
Radio Station Multipath Interference	114	0 - 429496729	
RDS Program Type		0 - 255	
RDS Quality Value		0 - 255	
RDS Station Identification Code		0 - 65535	
RDS Traffic Program Identification - Enhanced Other Networks Traffic Announcement Identification			
RDS Traffic Program Identification - Enhanced Other Networks Traffic Program Identification			
RDS Traffic Program Identification - Traffic Announcement Identification			
RDS Traffic Program Identification - Traffic Program Identification			
Short Critical Unlock Count		0 - 65535	
Tuned Radio Station Frequency		8750 - 11300	Hz
Tuner Bandwidth		0.20 - 2.75	Hz
USB Media Error Statistics - Cannot Read File		0 - 65535	
USB Media Error Statistics - File Format Not Supported		0 - 65535	

Disclaimer

This test report is for reference only for vehicle test and maintenance. The vehicle operating data provided in this report are all static data. The detailed dynamic diagnostic data can be read by professional maintenance device, and LAUNCH will not be liable for any accidents and failures arising therefrom!